

DAFTAR GAMBAR

Gambar 2. 1 Logo PT Yodaya Hijau Bestari	5
Gambar 2. 2 Struktur Organisasi PT. Yodaya Hijau Bestari	7
Gambar 3. 1 3D Visual Bangunan Bali International Hospital.....	10
Gambar 3. 2 3D Bangunan Bali International Hospital	11
Gambar 3. 3 Denah Lantai 1 Bali international Hospital	12
Gambar 3. 4 Denah Lantai 1 Bali international Hospital	13
Gambar 3. 5 Denah Potongan B-B Bali international Hospital.....	14
Gambar 3. 6 Gambar Tabel Ukuran dan Jumlah kaca	15
Gambar 3. 7 Gambar Tabel Total Perhitungan Luas Kaca	16
Gambar 3. 8 Gambar Tabel Luas Fasad	16
Gambar 3. 9 Gambar Tabel Data Luas Kaca	17
Gambar 3. 10 Gambar Tabel Luas Dinding.....	17
Gambar 3. 11 Gambar Tabel Total Perhitungan Fasad Sisi Utara	18
Gambar 3. 12 Gambar Tabel Perhitungan Luas Fasad seluruh Sisi Fasad	19
Gambar 3. 13 Ketentuan Batas WWR Menurut BGH.....	19
Gambar 3. 14 Gambar Tabel Hasil WWR Keseluruhan	20
Gambar 3. 15 Site Plan UIN Sunan Gunung Djati.....	23
Gambar 3. 16 Orientasi Bangunan UIN Sunan Gunung Djati	24
Gambar 3. 17 Denah Lantai 1 Gedung FEBI	24
Gambar 3. 18 Denah Lantai 2, 3, dan 4 Gedung FEBI	25
Gambar 3. 19 Hasil Perhitungan Fasad Gedung FEBI.....	26
Gambar 3. 20 Hasil Perhitungan Fasad Gedung ADM.....	27
Gambar 3. 21 Hasil Perhitungan Fasad Gedung FTK.....	27
Gambar 3. 22 Hasil Perhitungan WWR FEBI, ADM, dan FTK.....	28
Gambar 3. 23 Bird Eye View 3D Visual RS Anutapura Palu	30
Gambar 3. 24 File RS. Anutapura Palu	32
Gambar 3. 25 Tracing Denah Lantai 1	32
Gambar 3. 26 Tracing Denah Lantai 2, 3, 4, dan 5	33
Gambar 3. 27 Potongan RS Anutapura Palu	33
Gambar 3. 28 Aksonometri Gubahan RS Anutapura Palu.....	34
Gambar 3. 29 Logo Integrated Environmental Solutions (IES).....	35
Gambar 3. 30 Logo Ashrae	35
Gambar 3. 31 Site Plan RS Anutapura Palu	36
Gambar 3. 32 Hasil Simulasi Pola Edar Matahari RS Anutapura Palu	37
Gambar 3. 33 Contoh Denah yang Tumpang Tindih	38
Gambar 3. 34 Gambar Kesalahan Saat Pembuatan Gubahan.....	39